EPSON PRODUCT SUPPORT BULLETIN

 Date:
 1/10/2003
 Originator:
 PH


 PSB #:
 PSB.2003.01.001
 Authorization:
 #

 Reference:
 TE02-442
 Total Pages:
 1

Product(s): Stylus C80, C82, CX5200, Stylus Photo 960, 2200

Subject: Maintenance request message

This bulletin was created to inform you of the maintenance request message. When the following message appears, the waste ink pads inside the printer are full and need to be replaced. You should take the unit to your local servicer to do the replacement.



For information on finding your nearest authorized servicer contact Epson at 1-800-922-8911 or go to WWW.EPSON.COM.